



JON M. HUNTSMAN, JR.
Governor
GARY R. HERBERT
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director
JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

June 3, 2008

Supervisor CK

Mine Name: Tusher Redwood	Permit Number: S0190061
Operator Name: Larry Walker	Inspection Date: 5/8/08
Inspector(s): Tom Munson	Time: 9AM-10AM
Other Participants: Larry Walker	Mine Status: Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection: As a new inspector to this area, this inspection was mainly to find the site and assess the amount of disturbance.

Inspection Summary: I met Mr. Walker onsite and looked at the site that was less then 100 by 100 foot area where he had cleared minor amounts of overburden and is hand digging with a pick and shovel petrified wood. The site is accessed by foot. There was no trash on site and he operates the site continually as hand digging is very slow and there will be no new disturbance. We did not get an opportunity to go to his other site as he has one other small site were he does the same thing.

Photos were taken to document site conditions.

Conclusions and Recommendations:

Continue to monitor this sites when in the area.

Inspector's Signature

TM:pb

cc: (OPERATOR)

Becky_doolittle@blm.gov

O:\M019-Grand\S0190061-TusherRedwood\inspections\insp-S190061-05082008.doc